

Figure 8-3 on page 8-2 has the pinouts wrong. The corrected image should be as follows.

Figure 8-3: The Bus Mouse Pins

